To: McKean, Deborah[mckean.deborah@epa.gov]; Keteles, Kristen[Keteles.Kristen@epa.gov]

From: Schmit, Ayn

Sent: Thur 4/4/2013 10:29:22 PM
Subject: FW: Pavillion Monitoring Data
Pavallion Sample Results 07-12.xlsx

Just thought it would be useful for you to have this PWS data that the DW program pulled together awhile ago...

Ayn E. Schmit

303-312-6220

Water Policy Advisor

Office of Ecosystem Protection & Remediation

EPA Region 8, 1595 Wynkoop Street

Denver, CO 80202-2466

From: Ayn Schmit [mailto:Schmit.Ayn@epamail.epa.gov]

Sent: Tuesday, April 02, 2013 3:54 PM

To: Schmit, Ayn

Subject: Fw: Pavillion Monitoring Data

Ayn E. Schmit Water Policy Advisor

(PH) 303-312-6220 (FAX) 303-312-7150 EPA Region 8 1595 Wynkoop Street Denver, Colorado 80202-1129 schmit.ayn@epa.gov

----- Forwarded by Ayn Schmit R8, USEPA 'US on 04/02/2013 03:53 PM -----

From: Lisa Kahn/R8/USEPA/US
To: Schmit. Ayn:@epa_gov
Cc: Tsegaye Haifur/R8/USEPA/US@EPA, Sadie Hoskie/R8/USEPA/US@EPA
Date: 02/29/2012 02:23 PM
Subject: Fw: Pavillion Monitoring Data

Hi Avn.

Attached is a table of the town of Pavillion's monitoring data from 2007 to the present. For the chemicals most of the results are "0" which really means that they are less than the lab's detection limit. If you want more info on the detection levels, Tsegaye can provide that to you, but it gets complicated.

In general, the data show that the town has not exceeded any of the primary MCLs except for total coliform. Fluoride is detectable, but under the MCL. There is no MCL for sodium, and Pavillion's results were 240 mg/L in June 2008 and 270 mg/L in Aug 2011. Sulfate has a secondary MCL of 250 mg/L, and Pavillion's results exceed that secondary MCL with values of 392 mg/L in June 2008 and 439 mg/L in Aug 2011.

Here's the definition of secondary MCLs from the EPA website:

National Secondary Drinking Water Regulations (NSDWRs or secondary standards) are non-enforceable guidelines regulating contaminants that may cause cosmetic effects (such as skin or tooth discoloration) or aesthetic effects (such as taste, odor, or color) in drinking water. EPA recommends secondary standards to water systems but does not require systems to comply. However, states may choose to adopt them as enforceable standards.

The Town has had the following total coliform violations since 2003:

Failure to take 5 routine samples in Sept 2011

MCL in Oct 2007 (more than one total coliform positive sample in the month, but no E. coli positive samples)

Failure to monitor monthly in June 2003

Please let me or Tsegaye know if you need any more information about Pavillion's water supply. thanks, Lisa

Lisa Kahn Unit Chief, Drinking Water Unit A US EPA Region 8 Drinking Water Program 1595 Wynkoop St. (8P-W-DW) Denver, CO 80202 303-312-6896 kahn.lisa@epa.gov

---- Forwarded by Lisa Kahn/R8/USEPA/US on 02/29/2012 01:48 PM ----

From: Tsegaye Hailu/R8/USEPA/US To: Lisa Kahn/R8/USEPA/US@EPA Date: 02/28/2012 10:54 AM Subject: Pavillion Monitoring Data

Lisa,

Attached are PivotTables of monitoring data for the Town of Pavillion from 2007 to present. Rads data is not included system is on 9 year schedule. Past data is low and the next data is due in 2016.

(See attached file: Pavallion Sample Results 07-12.xlsx)

US EPA Region 8 Mailcode: 8P-W-DW 1595 Wynkoop Street Denver, Colorado 80202-1129 Tel: 303-312-6273

Toll-Free Fax:1-877-876-9101 Email: hailu.tsegaye@epa.gov